

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

IJ1189
East
> 1
1.565 mi.
8262 ft.

E 19TH ST & EMMONS AVE
E 19TH ST & EMMONS AVE
BROOKLYN, NY

NY Spills S102142656
N/A

Site 1 of 3 in cluster IJ

Relative:
Higher

Actual:
1 ft.

SPILLS:

Name: E 19TH ST & EMMONS AVE
Address: E 19TH ST & EMMONS AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9112402 / 1992-03-05
Facility ID: 9112402
Facility Type: ER
DER Facility ID: 258849
Site ID: 321323
DEC Region: 2
Spill Cause: Deliberate
Spill Class: Not reported
SWIS: 2401
Spill Date: 1992-02-06
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1992-03-05
CID: Not reported
Water Affected: SHEEPSHEAD BAY
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Citizen
Cleanup Ceased: 1992-03-05
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-03-11
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: NYC PARKS & REC
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks: "REFERED TO ECO'S."

All Materials:

Site ID: 321323
Operable Unit ID: 962734
Operable Unit: 01
Material ID: 417375
Material Code: 0180A
Material Name: creosote
Case No.: 08001589
Material FA: Hazardous Material
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported